

Report Date: November 30, 2020

Project: Cuyahoga County Buildings

Inspector(s): Julie Gue, Certified Technician

Inspection and Test Date(s):

June, 2020 – November, 2020

Duct Fabricators, Inc. “Fire Safety Division” summary of ongoing fire/smoke damper inspections within designated Cuyahoga county buildings. These dampers were inspected for proper installation. The dampers were then tested and photographed in the “open” and “closed” positions to confirm that they were functioning as designed.

Jane Edna Hunter Building – Complete

Metzenbaum Building – Complete

Cuyahoga County Animal Shelter – Complete

Justice Center Jail II – 93% Complete (delayed due to Covid-19)

Cuyahoga County Courthouse- 98% Complete
(Completion by December 11, 2020)

Virgil E Brown – 50% Complete. Actively in progress

We will continue to scan and label dampers on the mechanical prints as they become available through the County.

NOTES: NFPA 80, NFPA 101 and NFPA 105 require newly installed dampers to be inspected and tested one year after initial installation. Thereafter, dampers are to be visually inspected every two years and functionally tested every four years.

Additionally, the information contained herein verified whether the dampers were functional at the time of testing. This verification process does not represent any form of a guarantee that the dampers will properly perform in the future.