



T.H. Martin Fire/Smoke Damper Testing Report

Date: _____

LOCATIONS	NUMBER OF UNITS	VISUALLY INSPECTED	UNITS PASSED	REQUIRE REPLACEMENT/REQUIRE CODE REVIEW
Board of Elections	19	19	19	
County Courthouse	160	160	160	
Court House Square	24	24	24	
Metzenbaum	10	10	9	Screen impeding damper blinds will be replaced through contract with T.H. Martin.
Virgil Brown Building	397	397	397	
Jane Edna Hunter Building	13	13	13	
Animal Shelter	4	4	4	
Justice Center, Court Towers	915	915	915	
Jail I	388	388	388	
Jail II	450	450	450	
Juvenile Justic Center	495	495	495	
Sanitary Engineering	0	0	0	
Airport	0	0	0	
1642 Lakeside	2	2	2	
Bridge Garage		0	0	
Brookpark Garage	0	0	0	
Gerber Medical Examiner Building				Service inspection to be contracted by Ostendorf-Morris, LLC
York Road Yard	0	0	0	
Men's Homeless Shelter	Unknown due to remodel			Need access doors
Estimated Damper Count as of 9/1/13	2878	2878	2797	